


Ramond
Box 175
Ba, Ky

ATT: DWAYNE J. WHITE
PATENT EXAMINER
ART UNIT 3745



USPTO
CUSTOMER SERVICE WINDOW,
RANDOLPH BUILDING,
401 DULANY STREET,
ALEXANDRIA, VA 22314.
COMMISSIONER OF PATENTS
P.O. BOX 1450,
ALEXANDRIA VA 22313,
PHONE (571) 272-482



US9.

163745

10/804-709

ATT: DWAYNE J. WHITE
PATENT EXAMINER
ART UNIT 3745

USPTO
CUSTOMER SERVICE WINDOW,
RANDOLPH BUILDING,
401 DULANY STREET,
ALEXANDRIA, VA 22314.
COMMISSIONER OF PATENTS
P.O BOX 1450,
ALEXANDRIA VA 22313,
PHONE (571) 272-4825



Charles Raymond,
Inventor
Ph/Fax: (679) 667 8078
Appl No. 10/804/709
Dated: 25 - 10 - 05

USPTO
Customer Service Window,
Randolph Building,
401 Dulany Street,
Alexandria VA 22314.

Commissioner of Patent,
P.O.Box 1450,
Alexandria VA 22313.

Examiner Art Unit 3745
ATT - Dwayne J. White
Ph: (571) 272 4825

RECEIVED
NOV 02 2005
TECHNOLOGY CENTER R3700

Dear Mr. White,


Thank you for your patient guidance in this case. I have tried to follow your advice and am submitting a response to your first office action.

I apologize for not being more familiar with the correct terminology used by a patent attorney.

I have again put a claim that is generic, and it is followed by a dependent claim which could replace the generic claim if the generic claim won't fly. I couldn't see why the cited art would preclude allowing the claim however.

Again, the easiest way to reach me for clarification or required changes is by email raymond@connect.com.fj.

Thank you,


Charles Raymond

Transmittal

29 pages (Including address) of response

5 Pages of Photograph

Photos

- (A) Fig 6A shows pump intakes
Top shows intake, hole for shaft
Bottom shows concave housing with
two intakes into plenum area
Fig 6A is in drawings
- (B) Fig 1A shows direct coupled pump
Bottom shows jet stream.
Fig 1A is in drawings
- (C) Shows parts of pump in Fig 1A
tangential vane entry
- (D) shows hydromotor
Top foto shows two tangential
intakes similar to Fig 6A
Bottom foto shows rotor with
tangential vanes at rotor periphery
- (E) shows hydromotor with only
one side hooked up to show how
fluid goes straight through pump.
Rotor is turning 2750 rpm